



INSPECTION AND VALUATION OF VEHICLES

REG CARD : [] Yes [] No [] Pending
REG NO : CDJ4569
MAKE & MODEL : PERODUA ALZA 1.5
NAME OF HIRER :
AGREEMENT NO. :


PUSPAKOM INSPECTION VRI : [] Done [] Not Done
REPO. DATE : 13/08/2018
TRANSMISSION : [] Manual [X] Auto
YEAR OF MAKE :
PRESENTATION : [] Towed [X] Drive
SPECIFIC TYPE OF MODEL :
KEY : [X] Yes [] No
BRANCH : Selangor
ALARM : [] Yes [] No

SECTION A - EXTERIOR

Table with 4 columns: Yes/Good, No/Fair, Broken/Bad, Remark. Lists 20 exterior items like Paintwork, Emblem, Spot Light, etc.

SECTION D - GENERAL APPEARANCE

Overview : [] GOOD [X] FAIR [] BAD [] ACCIDENT UNIT



[] Chassis Tampered [] Engine Changed [] Roof Pillars [] Floor Board

SECTION B - INTERIOR

Table with 4 columns: Yes/Good, No/Fair, Broken/Bad, Remark. Lists 21 interior items like Dash Board, Meter Gauge, Clock, etc.

SECTION E - REMARKS ON OVERALL CONDITION OF THE VEHICLE

- * BUMPER DEPAN DAN BELAKANG RENGANG
* BODY KERETA CALAR DAN CAT TANGGAL
* BODY DEPAN KEMIK
* SKITTING DEPAN PECAH

SECTION F - DEFECT

SECTION G - TYRE

Front(Left) Brand:
Front(Right) Brand:
Rear(Left) Brand:
Rear(Right) Brand:

SECTION H - INSPECTION CONFIRMATION

Reposessed by : Acknowledged by storekeeper : Verified by staff:
Name : Name : Name :
I/C No : Co. chop : I/C No :
Tow Truck No :

SECTION C - ENGINE COMPARTMENT/BOOT

Engine No : G49A64U
Chassis No : PM2M502G002164124
1. Engine : [X] Yes [] No [] Dismantled
[X] Working [] Not Working

Table with 4 columns: Yes/Good, No/Fair, Broken/Bad, Remark. Lists 9 items like Gear Box, Clutch, Radiator, etc.